

VEHICLE INSPECTION REPORT

MD24UFY

Renault C 430

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 18/06/2024

Year 2024

Mileage 26,974 Km Not Warranted

Fuel Type Diesel

Colour WHITE

VIN VF630S160RD006391

Body Style Cement Mixer

MOT Due 17/06/2027

Cab Type DAY CAB

Gearbox AUTOMATIC

Axle Combi 8x2

Rear Suspension Steel

WARNING LIGHT ON DASH PMO BODY, SURROUND CAMERA SYSTEM, DOUBLE HUB REDUCTION

Tyres

NSF NSI1

NSI2 NSI3

NSI4

OSF OSI1

OSI2 OSI3

OSI4

Spare NSO1

NSO2 NSO3

NSO4

OSO1

OSO2

OSO3

OSO4

Features

- Park assist camera
- Air conditioning


Photos







Condition Check



Damage Photos



1: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



2: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



3: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK